ATS9625/ATS9626
Known Issues

Below is a list of known issues for ATS9625 and ATS9626.

Date Reported	Issue	Recommended Action
Sept. 21, 2023	A change to the Windows system power event monitoring in driver version 7.10.1 may cause issues when waking-up from sleep mode.	Use driver version 7.10.0 or lower.